

Hydrogen Sulphide

Easily identified by a 'rotten egg smell' caused by hydrogen sulphide contamination. This gas can easily and quickly permeate an entire premises with the offensive smell. It can also be very corrosive to piping, tanks and any metallic surfaces it contacts. The gas is caused by various strains of iron bacteria that live in iron piping and as they die they give off hydrogen sulphide and methane gas. Bacteria can often thrive in water heaters regardless of the type of piping.

Problems Caused by Hydrogen Sulphide

- Offensive 'rotten egg' smell that can permeate an entire home or building
- Corrosive effect on plumbing appliances & fixtures

Solution: Activated Carbon Filters

These filters are designed to deal with offensive odours, tastes and colours. Activated carbon has an almost unlimited ability to remove organic tastes from water; due to its chemical make-up and large surface area..

Benefits of Ultra Violet Disinfection Systems

- Purified, clean water
- No offensive odours
- Extended working life of plumbing appliances and fixtures

Perfect Water Systems Limited

Ballysally Business Park, Railway Road, Charleville, Co Cork.
Phone 063-89290

www.perfectwater.ie